# ServiceMyRide Used CarInspection

Order# [CG-DEL-081505]

Inspection Date 01-Nov-2020

#### Vehicle Details

Registration#	DL2CAB0069	Fuel	Diesel
Vehicle Make	Chevrolet	Model	Cruze
Manufacture Year 2013	2013	KM Reading	54169
<b>Chassis Number</b>	MA6JFDKDCCH0XXXXX	Engine Number	NA
Test Drive Taken Yes	Yes	No. ofOwners	1

Overall Rating And Recommendations



# **Recommendation By Experts:-**

- 1. Engine In Pristine Condition After Regular Maintenance
- 2. All 5 New Branded Tyres



# Projected Expenses

What	When	How much
General servicing	Now	4500
Coolant Fluid	Now	450
Wiper Blades	Now	450
Diesel Filter	Now	1950
<b>Brake Rotors</b>	10000 KM	6500

## Priority observations

Car Needs General Service
Car Paint is Overall Original
No Accidental Signs
Brake Rotors Needs Work

### Minor observations

Front Right Fender Repainted Front Left Door Paint

13850


















# Exterior Damage Che ck

- Represents visible dents on the body of the car (not frame)
- Represents visible scratches on the body
- Represents rust on the body (requires immediate attention)



- time of inspection without any prejudice. Errors, if any, are unintentional and shall be brought to our notice at the earliest. This report is created by Servicemyride.in after physical inspection of the vehicle and is based on the best judgment of technicians at the
- criterion or the final recommendation for purchasing or not purchasing. This report shall be used only as an input in the overall decision making process and should not be considered as sole decision making
- This Report does not entail Servicemyride in for any liable losses, damages to the car caused before or after sale of ca rto the next owner.